

Pasos inferiores de fauna en la NH-44 Kanha–Pench — Corredor de tigres verificado con cámaras trampa (Madhya Pradesh, India)

PES & Nature-Based Solutions · Buena práctica · India

Puntuación de calidad: 33/100

Solidez de la evidencia: Cautelar / limitada

Resumen

Nueve pasos inferiores bajo la NH-44, que atraviesan la Reserva de Tigres de Pench, incluidas dos estructuras de 750 m, registraron 468 imágenes de cámaras trampa de 15 especies en un estudio de 90 días del Instituto de Vida Silvestre de la India, con más de diez tigres documentados usando los pasos para mantener abierto el corredor Kanha-Pench.

Dimensiones clave

Dimensión	Puntuación
Carbon — sequestration / storage, evidenced	0/3
Biodiversity — conservation / improvement, evidenced	3/3
Water & soil — retention, infiltration, erosion control	0/3
Fire resilience — risk reduction, evidenced	0/3
Governance, certification & transferability	2/3

Evaluated by C-NAPSE

Fuentes de datos

[C-NAPSE web research](#) — consultado el 2026-09-04

[Wildlife Institute of India \(WII\); National Highways Authority of India \(NHAI\)](#) — consultado el 2026-09-04

[NTCA/WII: NH-44 \(NH-7\) Underpass Monitoring Report, 2020](#) — consultado el 2026-09-04

[The Better India: How India's First Dedicated Underpass for Wildlife Was Built](#) — consultado el 2026-09-04

[Rathore et al. 2012, PLoS ONE \(corridor connectivity study\)](#) — consultado el 2026-09-04

Citar — Evidoria. *Pasos inferiores de fauna en la NH-44 Kanha–Pench — Corredor de tigres verificado con cámaras trampa (Madhya Pradesh, India)*. ID persistente: 8bc8e4f1-519b-48ab-8744-2106a50f05f4.